

RELEASEnotes

T100-Series Torque Transducer: Stator

Thank you for choosing HBK's torque sensor T110/T100.

Your feedback is important for HBK. If you encounter any problems or suggestions to improve the T110/T100, please let us know.

You can contact our team of support engineers directly at <http://www.hbm.com/support>

Please always use the latest firmware version, available on the download section of the T100-Series website.

<https://www.hbkworld.com/en/products/transducers/torque/rotating/t110-t100#Downloads>

Version Overview – T100

Product name: T100

Patch: Improved power management,

Version: 1.0.44

Support other rotor size than 500Nm/1kNm

Date: 06.02.2026

*** The first Firmware Release for the T100-Stator was version 1.0.43**

Please always use the latest firmware and software version, available on T100 website

<https://www.hbkworld.com/en/products/transducers/torque/rotating/t110-t100#Downloads>

- End of file-